

Annexure D

BUILDING SAFETY CERTIFICATE

No. 398

Dated: 28/04/2025

It is certified that the existing building NATIONAL PUBLIC SCHOOL (name of the building or premises) at MAIN ROAD NEAR KANCHIYA, VPO CHHAJLI TEH. SUNAM DISTT. SANGRUR (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	1+2=3					

The building is owned/occupied by NATIONAL PUBLIC SCHOOL (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of PANCHAYATI RAJ (Name of Department/ Govt.) on 25/04/2025 (date of inspection) in the presence of PARVEEN AKHTAR VPO. CHHAJLI TEH. SUNAM (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 28-04-2025 for a period of ONE (1) years in accordance with rule and subject to compliance of the specific conditions as appended.

1. GROUND FLOOR
2. FIRST FLOOR
3. SECOND FLOOR
- 4.

Issued on 28/04/2025 at 03:00 PM by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.


Principal
National Public School
Chhajli (Sangrur)

Signature with Seal : 
Name : Sub Divisional Officer
Designation : Panchayati Raj, Sunam

Name & Address of Department/ Office: Parveen Akhtar

Secretary

Baba Farid Educational &
Social Welfare Society

No:- 398

Dated 28/04/2025


BUILDING SAFETY REPORT

Name of School: - **National Public School, Village Chhajli, Teh. Sunam, Distt. Sangrur.**

Our Department Technical team has visited the above mentioned school building along with School authorities and have visually inspected. The Building seems to be visually safe subject to the following observation & conditions.

- a) Parameters to check the stability and safety of building such as bearing capacity report, Structural Drawings, Test Reports of Material used Quality Control reports and certificates from Engineer in Charge for construction are not available.
- b) In case of any addition, alteration or expansion and modification to this building are done: certificate may be re-obtained after completion from undersigned.
- c) In case the building is affected by flood or if there is settlement of walls/foundation or sagging of roofs etc., immediate inspection of the undersigned be arranged to check the stability and safety of the building.
- d) A separate certificate regarding Fire Fighting should be obtained from the component authority.
- e) The owner of the building/Management is fully responsible regarding safety of building from all angles in spite of this report.
- f) Total covered area of the building is approx. **29500 Sft.**
- g) This report is not valid for legal purpose.
- h) This Building Consists of Only One block with three floors that is Ground floor, First Floor and Second Floor.
- i) This building visually seems safe to occupy for the normal use up to **March, 2026**


Principal
National Public School
Chhajli (Sangrur)


Sub Divisional Officer,
Panchayati Raj P.W. (C&M)
Sunam Udum Singh Wala.
Sub Divisional Officer
Panchayati Raj, Sunam


Secretary
Baba Farid Educational &
Social Welfare Society